

Grand Staircase-Escalante National Monument Road Report

Friday, July 28, 2017

**All road conditions can change RAPIDLY due to weather.
Please contact the nearest visitor center for the most current conditions.**

Roads to the East

Name	Date	Road	Comments
Burr Trail	7/15/2017	2WD	None
Notom-Bullfrog	7/26/2017	Impassable	Impassable due to deep mud and cut banks at wash crossings! (per Capitol Reef NPS report)
Road to Bullfrog Marina	7/26/2017	2WD High Clearance	2WD High Clearance Xing at Bullfrog has high water. (per Capitol Reef NPS report)
Wolverine Loop	7/23/2017	Impassable	East entry is 2wd with caution to Wolverine Canyon. Impassable from West entry to Horse Canyon
Cedar Wash	7/27/2017	4WD High Clearance	Very muddy where Alvey Wash crosses road near Hole in the Rock Road junction.
Hole in the Rock	7/27/2017	2WD, 2WD High Clearance	Washboarded. Some mud and standing water on road, but passable with caution. Recommend HC-4WD for last 7 miles.
Spencer Flat	7/27/2017	2WD High Clearance, 4WD High Clearance	Standing water and muddy road. Caution advised.

Roads to the North

Name	Date	Road	Comments
Hells Backbone	7/26/2017	2WD	Good condition. Washboards
Posey Lake to Loa	7/26/2017	2WD	Passable. Washboards.
Whites Flat (FR #152)	7/26/2017	2WD	Good condition
Griffin Top	6/26/2017	2WD	Passable. Clearance helpful in a few areas.
North Creek (FR #149)	7/26/2017	2WD High Clearance	2WD High Clearance some areas of mud possible.
Main Canyon	7/25/2017	2WD High Clearance	Debris has been removed, High Clearance from North-creek entrance.

Roads to the Central Areas

Name	Date	Condition	Comments
Smoky Mountain - Alvey Wash	7/27/2017	4WD High Clearance, Impassable	Very muddy to impassable where Alvey Wash crosses road near town of Escalante. Vehicle travel not advised until road dries.
Left Hand Collet	7/13/2017	4WD, 4WD High Clearance	4WD Rough and rocky with steep grades.
Croton	7/13/2017	2WD High Clearance, 4WD High Clearance	Rough, rocky, and remote. HC required, 4WD recommended.
Smoky Hollow	7/3/2017	2WD High Clearance, 4WD High Clearance	None

Roads to the West

Name	Date	Road	Comments
Cottonwood	7/26/2017	2WD High Clearance	2WD High Clearance, some road damage. Rain in forecast.
Skutumpah	7/26/2017	2WD High Clearance	2WD High Clearance, some road damage from recent flooding! Passable!
Glendale Bench	7/9/2017	2WD	2WD w caution to washboard, rough spots
Paria Movie Set	7/16/2017	2WD	2WD to picnic area, HC2WD beyond. Rain can affect road conditions.
House Rock Valley	6/18/2017	2WD High Clearance	Rough, rutted, rocky 2WD w good clearance
White House	7/26/2017	2WD, 2WD High Clearance	2WD/2WD High Clearance, high clearance needed for second crossing due to mud!

